

## Analysis of Abrasive wheels

---

Abrasive cutting wheels operate at very high speeds &ndash; low density regions within the wheel can be very hazardous.

CDD have combined Xray mass measurement with laser thickness measurement to accurately map the density across the parts. The system calculates the spot density of each point on a 0.5mm matrix across the entire surface of the wheel.&nbsp; Up to half a million points are scanned on each wheel, as part on an in-line inspection system.

This is used as part of a process monitoring system to ensure even deposition of the abrasive material.